


FALCON



NOTE:
 - A/C WITHOUT SATCOM ANTENNA :
 A MINIMUM TAL CLEARANCE OF
 7.23 m (23.89 ft) IS REQUIRED FOR
 THE HANGAR FLOOR TO CEILING
 - A/C WITH SATCOM ANTENNA :
 A MINIMUM TAL CLEARANCE OF
 7.90 m (25.92 ft) IS REQUIRED FOR
 THE HANGAR FLOOR TO CEILING
 - FOR A/C JACKING-UP,
 ADD 0.567 m (1.86 ft) TO THESE VALUES

CONFIGURATION	W	H1 FN LIGHT INCLUDED	H2 SATCOM TP FARING INCLUDED
MFW	19,141 Kg (42,200 lb)	6,990 m	7,047 m
	16.9% OF FORWARD MAX MAC	(22.93 ft)	(23.12 ft)
MLW	17,836 Kg (39,300 lb)	7,035 m	7,072 m
	14.2% OF FORWARD MAX MAC	(23.07 ft)	(23.20 ft)
MFW	10,650 Kg (23,479 lb)	7,195 m	7,173 m
	14% OF AFT MAX MAC	(23.59 ft)	(23.53 ft)
MFW	9,600 Kg (21,160 lb)	7,049 m	7,106 m
	32.5% OF FORWARD MAX MAC	(23.13 ft)	(23.31 ft)
MFW AND N/G SHOCK ABSORBER DEFLATED	10,650 Kg (23,479 lb)	7,302 m	7,259 m
	14% OF AFT MAX MAC	(23.94 ft)	(24.14 ft)
MFW AND N/G SHOCK ABSORBER DEFLATED	9,600 Kg (21,164 lb)	7,303 m	7,300 m
	32.5% OF FORWARD MAX MAC	(23.94 ft)	(24.12 ft)


Falcon 200EX EASy/DX/LX/S Aircraft

Line Maintenance

The line maintenance course is a condensed, 5-day session. It enables technicians to understand aircraft systems and servicing with an emphasis on practical experience to build aircraft maintenance skills.

Moderate troubleshooting is stressed and reinforced with hands-on sessions on available aircraft. Active student participation provides a better understanding of aircraft systems, leading to effective and efficient maintenance practices.

For operations with technician scheduling and cost limitations, this Falcon 2000 EX EASy/DX/LX/S class creates a highly productive solution.



**Course Length
5 Days (40 Hours)**

FAA IA Approval Code:

C-IND-IM-161031-K-010-001



Other GLOBALJET courses available for your Falcon 2000 EX EASy/DX/LX/S:

FAA Accepted

- Falcon 2000 EX EASy/DX/LX/S Gen-Fam*
- Falcon 2000 EX EASy/DX/LX/S Initial*
- Falcon 2000 EX EASy/DX/LX/S Refresher*
- Falcon 2000 EX EASy/DX/LX/S Electrical Interface*
- Falcon 2000 to Falcon 2000 EX EASy/DX/LX/S Differences*

For more information on your Falcon 2000 EX EASy/DX/LX/S please contact:

Sales@globaljetservices.com

30 Tower Lane →

Avon, CT → 06001

Tel (860) 651-6090 → Fax (860) 651-3618

globaljetservices.com

