


C E S S N A

Factory Authorized Training Provider

Citation 560 - V/Ultra/Encore Aircraft

Engine Rigging Maintenance Course



**Course Length
5 Day (40 Hours)**

FAA IA Approval Code:

C-IND-IM-130607-K-006-068



Other GLOBALJET courses available for your Citation 560 - V/Ultra/Encore:

FAA Accepted

- Citation 560 - V/Ultra/Encore Gen-Fam*
- Citation 560 - V/Ultra/Encore Line*
- Citation 560 - V/Ultra/Encore Refresher*
- Citation 560 - V/Ultra/Encore Electrical Interface*

TOPIC	Hrs
Introduction (1).....	0.5
Engine Review (72).....	4
Performance Runs & Procedures....	3
Static & Dynamic Rigging (Classroom)	4.5
Static Rig (on Aircraft).....	4
Dynamic Rig (on Aircraft).....	10
Troubleshooting (Partial or Re-Rigs, on Aircraft)	8
Reassemble, Safety, Log Entries	4
<u>Review, Lessons Learned</u>	<u>2</u>
TOTAL	40

This course will demonstrate and clarify the critical aspects of Citation 560 - V/Ultra/Encore engine rigging. While OEM manuals can present the necessary parameters and specs, it does not adequately describe the rigging process interrelationships and influencing factors. To compound matters, typical time constraints imposed on the technician often prevent a more thorough understanding of the rigging exercise.

This course offers a concise, practical procedure to follow for the technician to successfully rig a Citation 560 - V/Ultra/Encore engine and controls system. Students completing this course will extend their skills and value to the operations team.

Prerequisites:

- Use of an aircraft that can be rigged and operated over the course of 4 days
- Limited to 4 technicians

Additional Benefits:

- Upon completion of the rig, appropriate maintenance record entries (14CFR 43.9) will be completed for the aircraft
- A fully annotated, color-coded training workbook is provided

PLEASE NOTE: Successful student learning experience completely depends on the actual performance of complete rigging on a Citation 560 - V/Ultra/Encore. Customer aircraft availability from midday Day 2 through end of Day 5 needs to be ensured. Once actual rigging has commenced, the aircraft may not be able to be returned to service on short notice.

For more information on your Citation 560 - V/Ultra/Encore please contact:

Sales@globaljetservices.com

30 Tower Lane →

Avon, CT → 06001

Tel (860) 651-6090 → Fax (860) 651-3618

globaljetservices.com

